



Hello, Adam!

You have 3 appointments today! Please be on time and notify your customers once you are at the venue. You got this!





Jobs







B 1234 AB

B 1234 AB

Service

Repair

8:00 AM

8:00 AM

Pending

Pending


B 1234 AB

Details Progress History O Customer **Ben Andrew** Ben@gmail.com Lisa Bonet Lisa@gmail.com Alternate driver Vehicle ్ల్క్ Service

< Service

Det	ails	Progress	History	
Tasks				
	O St	r igate tart Journey rrival		
		ST/	ART JOURNEY (>)	
	Pre-	Inspection		
	Repair Order			
	Serv	ice In-Progress		
	Serv	Service Invoice		

Inspection Data



Let's Start

9:41



< Service

Deto	ils Progress History	
Tasks		
	Navigate Start Journey 12:30 pm Arrival	
	START JOURNEY (5)	
	Pre-Inspection	
	Repair Order	
	Service In-Progress	
	Service Invoice	

Inspection Data

< Service

Det	ails	Progress	History
Tasks			
•	Navi	gate	
	● Pe	Inspection erform Pre-Inspection and Pre-Inspection PRE	on -INSPECTION ()
	Repo	air Order	
	Servi	ice In-Progress	
		ice In-Progress	

< Service

Deta	ails	Progress	History		
Tasks					
•	Navi	gate			
•	Pre-	Inspection			
	• Ro	air order epair Order igned Document UPLOAD Ri	EPAIR ORDER (>)		
	Serv	ice In-Progress			
	Serv	Service Invoice			

Inspection Data



Repair Order

Repair Order Number

Enter repair order number

Attachment



Browse Files

Maximum uploads 5 files



Repair Order

Repair Order Number

A123456789



Attachment



Browse Files

Maximum uploads 5 files


Cancel

Photos

Albums

Q Photos, People, Places...








< Repair Order

Repair Order Number



Attachment






< Repair Order

Repair Order Number

A123456789

Attachment



9:41



< Service

Dete	ails	Progress	History		
Tasks					
•	Nav	igate			
	Pre-	-Inspection			
	• R	o air order Repair Order Signed Document	12:30 pm VIEW ③		
	Serv	vice In-Progress			
	Serv	Service Invoice			
	Insp	Inspection Data			

< Service

Deta	ils	Progress	History
Tasks			
	Navi	igate	
•	Pre-Inspection		
	Rapair Order		
•	Service In-Progress		
	Post-Inspection		
	Insr	pection Data	
		tart Inspection Data	1

End Inspection Data

START (>)

Inspection List

General	>
Front Tyre	>
Rear Tyre	>
Lubricants	>
Battery	>
Next Service	>
Fluid Level	>
Miscellaneous	>

Left Front Tyre	Right Front Tyre
Brand	
Select Brand	~
Manufacturer Date	
DD MM YYYY	
Thread Tickness (mm)	
Fill in thread thicknes	SS
Break Pad Tickness (mm)	
Fill in break pad thic	kness
Apply same details t	o all tyre
So	IVA

Left Front Tyre	Right Front Tyre		
Brand			
Select Brand	~		
A-Plus			
Accelera			
Achilles			
Admiral			
Aeolus			

Apply same details to all tyre

Left Front Tyre	Right Front Tyre
Brand	
Am	~
American Classic	
Amtel	
Antares	
Amtel	
Antares	

Save



Left Front Tyre

Right Front Tyre

Brand




Manufacturer Date



<		September 1990					
SUN	MON	TUE	WED	THU	FRI	SAT	
1	2	3	4	5	6	7	
8	9	10	11	12	13	14	
15	16	17	18	19	20	21	
22	23	24	25	26	27	28	
29	30	31					

Save



Right Front Tyre
×
×
o all tyre

Save